


New Side Panel and Outer Casing

Side Panel

As part of our quality improvement policy, we are introducing a new side panel which includes a grommet (see illustration) the grommet prevents cable ruptures at the cable entry point.


New grommet P/N 3865006



Outer Casing

The outer casing has been changed to ensure a better fit with the new side panel (see illustration below).

Bigger hole to fit the new grommet



New cable holder kit
P/N 9991069-ASSY



Servicing New and Old Models

Side Panel and Outer Casing

- a. When an existing side panel needs to be replaced, replace it with the same type of side panel.
- b. When an existing outer casing needs to be replaced, use a new outer casing and new side panel with grommet.

Notes

- When servicing the new models order the new outer casing and the new side panel.
- The new side panel does not fit the old outer casing.
- The old side panel does not fit the new outer casing.
- You must keep both types of side panels in stock.
- You may only use the new outer casings for the old 2X2 once the old stock has run out.

Serial Numbers for New 2X2 Parts

| Description | Part Number |
|-------------------------|--------------|
| Side panel with grommet | 9995059 |
| Side panel | 9995069 |
| Outer casing | 9995193 |
| Cable holder | 9991069-ASSY |
| Grommet | 3865006 |



Rainbow Pool Products

PO Box 2388, Mansfield Qld 4122

Telephone STD 61-7-3849 5385

Facsimile STD 61-7-3849 5384

Email: info@rainbowpoolproducts.com.au

Web: www.rainbowpoolproducts.com.au